



Hey looking at this and the works

This was glued back down at the time as the building report requested and you can see the orange glue there also.

More so the water ingress is now showing on the left hand end where I have circled in red, This was not a problem at time of report, So in turn this would just be ongoing monitoring and maintenance

See below I have circled in red where the moisture is showing internally

94A Chelsea St



⏮️ ∨ Reply all

